

For Release
Feb. 9, 1939

By Major A. H. Thiessen
Science Service Meteorologist

Frost penetration! How deep water pipes must be placed to escape freezing is a practical question. To get exact information, since it varies considerably, it is best to ask local plumbers or a local Weather Bureau Office. In this country frost penetrates from an inch in the South to over 60 inches on an average in northern Minnesota and Maine. In very cold winters the extreme measurements were 100 inches in Minnesota and 108 inches in northern Maine. As a rule the deepest penetrations may be expected in the interior of United States and Canada, where climate is of continental type.
